

Draw the shear stress and the normal stress for the points 1 – 5 (the centroid axis is through 3). Make the length of the arrow represent the magnitude of the stress.

